

Intel® PRO/10/100/1000/Wireless Software Release 6.1 Gold +CAT
3DES V6.1C0210, TIC 37544
NoSec V6.1C0532, TIC 37545
Pacific City

Incremental Changes Document
From Intel® PRO/10/100/1000/Wireless Software Release 6.1 Release Candidate
Build V6.1C0394, TIC 35430

Intel Confidential – Controlled Access

3/21/2002

This document as well as the software described in it is furnished under license and may only be used or copied in accordance with the terms of the license. The Information in this manual is furnished for Informational use only, is subject to change without notice, and should not be construed as a commitment by Intel Corporation. Intel Corporation assumes no responsibility or liability for any errors or inaccuracies that may appear in this document or any software that may be provided in association with this document.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or Infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Except as permitted by such license, no part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means without the express written consent of Intel Corporation.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copyright © Intel Corporation 2002

*Third-party brands and names are the property of their respective owners.

Component List		Component List	
Pacific City NoSec 6.1		Pacific City NoSec 6.1	
V6.1C0394	2/21/02 1:25 PM	V6.1C0532	3/21/02 11:49 AM
Component Name	Version	Component Name	Version
Acrobat Reader	5.0	Acrobat Reader	5.0
ANS_Install_Intel	5.0.8.0	ANS_Install_Intel	5.0.8.0
ANS_Netware_All	Ans5.15	ANS_Netware_All	Ans5.15
ANS_NT4_All	5.31.00.0000	ANS_NT4_All	5.31.00.0000
ANS_UnixWare_All	3.06	ANS_UnixWare_All	3.06
ANS_W2K_ALL	5.31.00.0000	ANS_W2K_ALL	5.31.00.0000
ANS_WIN64_ALL	5.31.00.0000	ANS_WIN64_ALL	5.31.00.0000
BootAgentRISInstall_W2000_Intel	2.00	BootAgentRISInstall_W2000_Intel	2.00 Update 3
BootROM_Farmington2_Intel	4.1.02	BootROM_Farmington2_Intel	4.1.03
BootROM_PXE_Gigabit	v1.1.02	BootROM_PXE_Gigabit	v1.1.03
BootROM_PXE_Serverdemo_3rdparty	1.1	BootROM_PXE_Serverdemo_3rdparty	1.1
Cardbus_CBCombo_Intel	5.0.1	Cardbus_CBCombo_Intel	5.0.1
Cardbus_Scripts_Intel	3.0cb	Cardbus_Scripts_Intel	3.0cb
Cardbus_Uutilities_Intel	5.0.2a	Cardbus_Uutilities_Intel	5.0.2a
CAT-File_Dummy_All	2.0	CAT-File_Dummy_All	2.0
CAT-File_Islandia PRO Wireless RP CD	3.0	CAT-File_Islandia PRO Wireless RP CD	3.0
CAT-File_Reedsport_Cardbus	5.0.2	CAT-File_Reedsport_Cardbus	5.0.2
CHSM_8254x_All	6.58b	CHSM_8254x_All	6.59
CHSM_8255x_All	5.20	CHSM_8255x_All	5.18
Diag100_8255x_All	4.49a	Diag100_8255x_All	4.51
Diag1000_Kodiak_All	4.0.6.2	Diag1000_Kodiak_All	4.1.8.3
DMI_Win32_Intel	3.00.17.0012	DMI_Win32_Intel	3.00.18.0000
DMI-SNMP_DMI-SP	V3.00.07	DMI-SNMP_DMI-SP	V3.00.07
DOSODI_8255x_All	4.01	DOSODI_8255x_All	4.01
DOSODI_Gigabit_Intel	1.20	DOSODI_Gigabit_Intel	1.20
IE_CardBus_Guide_Common	1.9	IE_CardBus_Guide_Common	1.9
IE_CardBus_Guide_Intel_English	6.1.0.2	IE_CardBus_Guide_Intel_English	6.1.0.2
IE_Common_Guides_Intel_English	6.1.0.8	IE_Common_Guides_Intel_English	6.1.0.8
IE_Desktop_100_Guide_Intel_English	6.1.0.11	IE_Desktop_100_Guide_Intel_English	6.1.0.11
IE_Desktop_1000_Guide_Intel_English	6.1.0.11	IE_Desktop_1000_Guide_Intel_English	6.1.0.11
IE_Farmington3_Guide	6.1.0.3	IE_Farmington3_Guide	6.1.0.3
IE_Fort_Stevens_Priority_Packet_2_Intel	1.0	IE_Fort_Stevens_Priority_Packet_2_Intel	1.0
IE_FreeBSD	2.4	IE_FreeBSD	2.4
IE_Guides_Main_Retail_English	6.1.0.4	IE_Guides_Main_Retail_English	6.1.0.6
IE_Itanium_Guide_Intel_English	6.1.0.10	IE_Itanium_Guide_Intel_English	6.1.0.10
IE_Linux_General	4.4	IE_Linux_General	4.4
IE_PROSet2_Intel_English	6.1.0.6	IE_PROSet2_Intel_English	6.1.0.6
IE_Readme_6.0_Intel_English	6.1.0.6	IE_Readme_6.0_Intel_English	6.1.0.7
IE_Regulatory_QI_HTML_Intel	6.1.0.0	IE_Regulatory_QI_HTML_Intel	6.1.0.0
IE_Robohelp_DLL	1.1	IE_Robohelp_DLL	1.1
IE_Server_100_Guide_Intel_English	6.1.0.9	IE_Server_100_Guide_Intel_English	6.1.0.9
IE_Server_1000_Guide_Intel_English	6.1.0.9	IE_Server_1000_Guide_Intel_English	6.1.0.9

IE_Tools_Diag	6.1.0.3	IE_Tools_Diag	6.1.0.3
IE_Wireless_Admin_Guide	1.5	IE_Wireless_Admin_Guide	1.5
IE_Wireless_Guide_Adapter_2011B	1.7	IE_Wireless_Guide_Adapter_2011B	1.8
IE_Wireless_Guide_Adapter_5000	1.6	IE_Wireless_Guide_Adapter_5000	1.7
IE_Wireless_Guide_AP_2011B	1.9	IE_Wireless_Guide_AP_2011B	2.1
IE_Wireless_Guide_AP_5000	1.6	IE_Wireless_Guide_AP_5000	1.8
IE_Wireless_Guide_APHelp_2011B	1.3	IE_Wireless_Guide_APHelp_2011B	3.1.1.0
IE_Wireless_Guide_APHelp_5000	1.3	IE_Wireless_Guide_APHelp_5000	1.3
IE_Wireless_Guide_Common_Intel_English	2.0	IE_Wireless_Guide_Common_Intel_English	2.1
IE_Wireless_Readme	1.6	IE_Wireless_Readme	1.6
IE_WLO_Islandia_PROSet2_Help	3.1.0.4	IE_WLO_Islandia_PROSet2_Help	3.1.0.4
Inf_PRO_NT4_Intel	6.0.06	Inf_PRO_NT4_Intel	6.0.06
Inf_PRO100_Intel	6.1.2	Inf_PRO100_Intel	6.1.3a
Inf_PRO1000_Intel	6.1.5.6111	Inf_PRO1000_Intel	6.1.6.6114
INTEL_SNMP_MIB	1.2.5.0	INTEL_SNMP_MIB	1.2.5.0
MAKEDISK_PACCITY_GUI_INTEL	2.06a	MAKEDISK_PACCITY_GUI_INTEL	2.06a
MAKEDISK_PACCITY_INTEL	1.73	MAKEDISK_PACCITY_INTEL	1.73
MI_AutoRun	6.1.2.0	MI_AutoRun	6.1.2.0
MI_Core	6.1.8.061	MI_Core	6.1.16.061
MI_PROSetupNT4	1.2	MI_PROSetupNT4	1.2
MI_Setup	6.1.2.0	MI_Setup	6.1.2.0
NATIVE_SNMP_NW	LANAgent1.15	NATIVE_SNMP_NW	LANAgent1.15
NATIVE_SNMP32_MSI	1.13.0.0	NATIVE_SNMP32_MSI	1.13.0.0
NATIVE_SNMP64_MSI	1.13.0.0	NATIVE_SNMP64_MSI	1.13.0.0
NDIS_Coinstaller_W2k_All	1.07	NDIS_Coinstaller_W2k_All	1.07
NDIS_Colninstaller_W9x_Intel	6.0.0	NDIS_Colninstaller_W9x_Intel	6.0.0
NDIS_Uninstaller_Intel_W2k	4.10	NDIS_Uninstaller_Intel_W2k	4.10
NDIS_Uninstaller_Intel_W9x	4.09	NDIS_Uninstaller_Intel_W9x	4.09
NDIS_Uninstaller_Intel_Win64	4.11a	NDIS_Uninstaller_Intel_Win64	4.11a
NDIS2_8255x_All	4.31	NDIS2_8255x_All	4.31
NDIS2_Gigabit_All	1.23	NDIS2_Gigabit_All	1.25
NDIS3_8255x_All	6.1.2	NDIS3_8255x_All	6.1.3a
NDIS4_8255x_All	6.1.2	NDIS4_8255x_All	6.1.3a
NDIS4_PacificCity6.1_PRO1000_ALL	6.1.11.0	NDIS4_PacificCity6.1_PRO1000_ALL	6.1.14.0
NDIS5_8255x_All	6.1.2	NDIS5_8255x_All	6.1.3a
NDIS5_PacificCity6.1_PRO1000_ALL	6.1.11.0	NDIS5_PacificCity6.1_PRO1000_ALL	6.1.14.0
NDIS51_8255x_All	6.1.2	NDIS51_8255x_All	6.1.3a
NLM-Commonfiles	10-100-1000 V2.1	NLM-Commonfiles	10-100-1000 V2.1
NMS_INCLUSION_LIST_INTEL	Version 6	NMS_INCLUSION_LIST_INTEL	Version 6
NMS_WIN32_Intel	2.1.6.0	NMS_WIN32_Intel	2.1.9.0
NMS_WIN64_Intel	2.1.6.0	NMS_WIN64_Intel	2.1.9.0
NT4Updt_Intel	1.01	NT4Updt_Intel	1.01
OS2ODI_8255x_All	2.19	OS2ODI_8255x_All	2.19
PriorityPacket2_Intel	V2.29	PriorityPacket2_Intel	V2.29
Proset+_Win95_Intel	3.203	Proset+_Win95_Intel	3.205
PROSetII-Intel	5.3.6.0a	PROSetII-Intel	5.3.7.0
PROSetII-Reg_All	6.12	PROSetII-Reg_All	6.13
Setup_BaseDriver_Install	6.1.3.0	Setup_BaseDriver_Install	6.1.6.0

Setup_MI_64	6.1.09.061a	Setup_MI_64	6.1.17.061
Setup_NMS_IS_Intel	18	Setup_NMS_IS_Intel	18
Setup_PC_Setup64	1.4	Setup_PC_Setup64	1.4
Setup_PriorityPacket2_IS_Intel	13	Setup_PriorityPacket2_IS_Intel	13
Setup_PROSet_MSI	6.1.12.061a	Setup_PROSet_MSI	6.1.17.061
Setup_PROSet_PROSetExe	1.0.7.0	Setup_PROSet_PROSetExe	1.0.7.0
Setup_PROSet2_IS_3264_Intel	3.2	Setup_PROSet2_IS_3264_Intel	3.2
Setup_PROSet2_IS_Intel	27	Setup_PROSet2_IS_Intel	27
Setup_PROSet64_MSI	6.1.12.061a	Setup_PROSet64_MSI	6.1.16.061
Tools-Diag100_EFI_Intel	1.08	Tools-Diag100_EFI_Intel	1.08
Tools-Diag1000_EFI_Intel	4.0.6.2	Tools-Diag1000_EFI_Intel	4.1.8.3
Tools-IBACfg_All_Intel	v1.03	Tools-IBACfg_All_Intel	v1.04
Tools-IBAUtl_DOS_Intel	v1.09_g1102_e4102	Tools-IBAUtl_DOS_Intel	v1.12_g1103_e4103
Tools-IntelBootAgent_Readmes_All_Intel	Feb192002	Tools-IntelBootAgent_Readmes_All_Intel	Feb192002
Tools-IntelIdd	1.0.7.1	Tools-IntelIdd	1.0.7.1
Unattended_Install_All	PacificCity60_2.1	Unattended_Install_All	2.3
Unattended_Update_NT	2.22	Unattended_Update_NT	2.22
Unattended_Update_Win2k	1.8.3	Unattended_Update_Win2k	1.8.3
Unattended_Update_Win9x	3.2	Unattended_Update_Win9x	3.2
Unattended_Update_WinXP	1.0	Unattended_Update_WinXP	1.0
UNIX-SCO5_8255x_Intel	1.5.8	UNIX-SCO5_8255x_Intel	1.5.8
Unix-Solaris_8254x_PacificCity_Intel	3.3.5	Unix-Solaris_8254x_PacificCity_Intel	3.3.5
Unix-UW7DDI8_8254x_Ravenbay_Intel	6.1.9	Unix-UW7DDI8_8254x_Ravenbay_Intel	6.1.10
UNIX-UW7DDI8_8255x_Intel	2.3.19	UNIX-UW7DDI8_8255x_Intel	2.3.19
WBEM_NIC_2_INTEL	2.00.23.06	WBEM_NIC_2_INTEL	2.00.23.06
WBEM_NIC_2_WIN64_INTEL	2.00.23.04	WBEM_NIC_2_WIN64_INTEL	2.00.23.04
WBEM_PXE_Intel	v4.00.0.17	WBEM_PXE_Intel	v4.00.0.17
WBEM_QoS_Intel	1.00.20.02	WBEM_QoS_Intel	1.00.20.02
Win64_NDIS5_8255x_All	6.1.2	Win64_NDIS5_8255x_All	6.1.3a
WLO_NDIS4_Intel	3.0.9.0	WLO_NDIS4_Intel	3.0.9.0
WLO_NDIS5_Intel	3.0.7.0	WLO_NDIS5_Intel	3.0.7.0
WLO_WLANUnist_Win32_Intel	3.1.0.0	WLO_WLANUnist_Win32_Intel	3.1.0.0
WLO_NCPA_Win32_Intel	3.1.0.7b	WLO_NCPA_Win32_Intel	3.1.0.7b
WLOSetupIslandia_Win32_Intel	3.1.1.0	WLOSetupIslandia_Win32_Intel	3.1.1.0
WLOSetupSiteSurvey_Win32_Intel	3.0.7.0	WLOSetupSiteSurvey_Win32_Intel	3.0.7.0
WLOSetupWinCE_Win32_Intel	3.1.0.5	WLOSetupWinCE_Win32_Intel	3.1.0.5
WLOSetupWLANUtil_Win32_Intel	3.0.7.0	WLOSetupWLANUtil_Win32_Intel	3.0.7.0
WLOWirelessMakeDisk_Win32_Intel	3.1.4.0	WLOWirelessMakeDisk_Win32_Intel	3.1.4.0
WOL558-VXD	v1.05a	WOL558-VXD	v1.05a

Pacific City NoSec 6.1 Change Log

Newest Build: TIC = 37348 V6.1C0519

Previous Build: TIC = 35430 V6.1C0394

BootAgentRISInstall_W2000_Intel 2.00 Update 3

2.00 Update 3

Including updated tool built into the image.

2.00 Update 2

This build contains files that address the following showstopper: Fixed 16468 Soldotna's not booting on 440ZX systems. The ACPI scanning code was causing system hangs only on the 440ZX chipset. Added code to not try scanning on the 440ZX.

2.00 Update 1

Updating with the most recent version of tools.

BootROM_Farmington2_Intel 4.1.03

4.1.03

Fixed showstopper 16468 Soldotna's not booting on 440ZX systems. The ACPI scanning code was causing system hangs only on the 440ZX chipset. Added code to not try scanning on the 440ZX. All three systems in the Tracker all had the same chipset.

BootROM_PXE_Gigabitv1.1.03

v1.1.03

Fixed showstopper 16468 Soldotna's not booting on 440ZX systems. The ACPI scanning code was causing system hangs only on the 440ZX chipset. Added code to not try scanning on the 440ZX. All three systems in the Tracker all had the same chipset.

v1.1.02

Fixed 16062 - Double Eldridge with RPL link goes away. The Double Eldridge could not get link with RPL. The EXT_CTRL register was being corrupted in 3 locations. One was removed (the code was an unsupported legacy gigabit adapter) the others were solved by reading the register before ORing the needed bits.

Fixed 14136 - PXE Eeprom checksum error - Sterling / Itanium

The boot agent would report a checksum error on Itaniums. The access mode to the hardware doesn't work on IA-64 since there is no port addressing. When IA-64 was removed as a supported environment by 16139, this issue became irrelevant.

Fixed 16139 - Boot Agent prevents IA-64 system from Booting. The boot agent would not allow an IA-64 system to boot to the EFI shell. The Boot agent was scanning for ACPI tables as part of the Simple Boot Flag check. Since EFI (and thus IA-64) has a very different ACPI table method, this would cause the system to hang. Removing support for PXE on IA-64 removed this as an issue. The IA-64 processor type is checked by using the CPUID instruction and validating for Itanium, codename McKinley, and all future IA-64 processors that set bit 30 in the features list of function 1 of CPUID. Added a display message to EEPROM checksum error so that end users will know what generated the error message, and what version of the boot Agent generated it..

CHSM_8254x_All 6.59

6.59
Version change only.

CHSM_8255x_All 5.18

5.18
Added support for new Lavon A1 string branding to pass Novell certification tests

Diag100_8255x_All 4.51

4.51
Version of Kinnereth was changed

4.50
ICH5 was updated.

4.49a
The Copyright was updated.

Diag1000_Kodiak_All 4.1.8.3

4.1.8.3
Added message "Reading Adapter Configuration..." which displays when the user selects "View Adapter Configuration" option from "Main Menu". Increased max wait for link status check to 4 seconds because some adapters take a few seconds to establish link after an adapter reset.

4.1.8.2
Fixed the View Adapter Configuration menu to display adapter link status correctly. Rolled rev to 4.1.8.2.

4.1.8.1
Network test now sends 5000 packets instead of 500. This build is using new CUDL binaries to fix sender/responder bug.

4.1.8.0
Added code for external loopback test on 82540EM silicon. Modified to compile with NAL 0.72.64.0 and CUDL 0.98.04.0.

4.0.7.1
DIAG1000 v4.0.7.1
Fix to include copyright string in version and usage statements.
Fixed to display correct description string.
Compiles with NAL 0.57.62.1, CUDL 0.97.5.1, GAL 0.94.0.5.

DMI_Win32_Intel 3.00.18.0000

3.00.18.0000
PC6.1 Build, Added support for Kenai-32 for Windows 98

IE_Guides_Main_Retail_English 6.1.0.6

6.1.0.6
Changes the link at the top of the page to the wireless guides for Islandia 3.1.1

6.1.0.5

Removed "What's new" section in release.htm. Added version number. Changed directory for link to compact flash guide, was wireless/guides/cf. changed to wireless/guides/adapter/cf

IE_Readme_6.0_Intel_English 6.1.0.7

6.1.0.7

Repairing a show stopper in wiredpci.txt

IE_Wireless_Guide_Adapter_5000 1.7

1.7

Updated installation information in the PDF.

6.1.1.0

Added 5000_adpt.pdf

IE_Wireless_Guide_AP_2011B 2.1

2.1

fixed spelling errors in 2.3_led, 2.4_ap_features, 3.3_basic_settings, 3.5b_encryption_key, 3.9_config_filters.htm. fixed SCR 718 by stating meaning of WLAP acronym, several files affected. SCR 757 already fixed.

2.0

Changed sentence in step 3 of To copy the help files to a network web server. Fixed SCR718.

IE_Wireless_Guide_AP_5000 1.8

1.8

Config.htm: Modified file corrects erroneous path to AP Help file on CD. 5000_ap.pdf. Updated LED information.

1.7

Updated files from Paul, fixing broken links, revising setup for 3.1.1.

IE_Wireless_Guide_APHelp_2011B 3.1.1.0

3.1.1.0

Text edits

1.5

Fixed italics by converting to bold and spelling errors

1.4

Text edits

1.3

Updated with edits to the legal disclaimer

IE_Wireless_Guide_Common_Intel_English 2.1

2.1

Changes implemented to \wireless\guides\common\specs.htm: implemented PME updates and corrections to 5000 CardBus Adapter, PCI Adapter, and AP specifications.

2.0

Finished adding feedback from editors

Inf_PRO100_Intel 6.1.3a

6.1.3a

HCT 10 with QFE5 inf checker found a syntax issue with neti557x.inf (XP part).
This is certification issue.

6.1.3

Changed version and date to support v6.1.3 release for PC 6.1

Inf_PRO1000_Intel 6.1.6.6114

6.1.6.6114

Updated driver version.

6.1.6.6113

Updated driver version.

6.1.6.6112

- Removed TcpSegmentation parameter from XP INF for Livengood.

MI_Core 6.1.16.061

6.1.16.061

New Base driver MSM

6.1.15.061

New version of PROSetp.reg component (6.13)

6.1.14.061

New NMS and Wireless PROSet MSMs

6.1.13.061

New MCD MSM versions

6.1.12.061

Fixed Showstopper 16238 for base driver install

6.1.11.061

Include NMS 2.1.8.0

6.1.10.061

New SNMP version(1.13.0.0)

6.1.9.061

Include PROSet 5.3.7.0 and NMS 2.1.7.0.

NDIS2_Gigabit_All 1.25

1.25

Fixed bug - the driver's PCI scanning routine (ScanAllPciSlots) was not allowing for multiple NICs with differing device ids.

1.24

Moved some variables for large eeprom access in EEPROM.ASM to the

IDATA segment. OS/2 needs to access these variables offset from DS.
Please don't rely on CS offsets in this driver.

NDIS3_8255x_All 6.1.3a

6.1.3a
Fixed installation issue with Windows 95 and Windows Nt.
Updated ASF actions.

6.1.3
Special release for PC 6.1 v6.1.3. Fixed installation issue with NT4 and Windows 95.

NDIS4_8255x_All 6.1.3a

6.1.3a
Fixed installation issue with Windows 95 and Windows NT. Updated ASF actions.

6.1.3
Special release for PC 6.1 v6.1.3
- Fixed installation issue with NT4 and Windows 95.

NDIS4_PacificCity6.1_PRO1000_ALL 6.1.14.0

6.1.14.0
Fixed bug with determining size of receive buffers.

6.1.13.0
Driver now allocates the correct size receive buffers when running on 82542
with Jumbo Frames enabled.

6.1.12.0
- Added option to enable interrupts in CheckForHang instead of at init time. This code was added while
investigating SCR #16310 and 16068.- Fixed SMBUS access with Kenai32.

NDIS5_8255x_All 6.1.3a

6.1.3a
Fixed installation issue with Windows 95 and Windows Nt.
Updated ASF actions.

6.1.3
Special release for PC 6.1 v6.1.3
- Fixed installation issue with NT4 and Windows 95.

6.1.2
Fixed Tracker 16377
Wake on Lan certification failures

NDIS5_PacificCity6.1_PRO1000_ALL 6.1.14.0

6.1.14.0
Fixed bug with determining receive buffer size.

6.1.13.0

Driver now allocates the correct size receive buffers when running on 82542 with Jumbo Frames enabled.

6.1.12.0

- Added option to enable interrupts in CheckForHang instead of at init time. This code was added while investigating SCR #16310 and 16068.
- Fixed SMBUS access with Kenai32.

NDIS51_8255x_All 6.1.3a

6.1.3a

Fixed installation issue with Windows 95 and Windows NT. Updated ASF actions.

6.1.3

Special release for PC 6.1 v6.1.3

- Fixed installation issue with NT4 and Windows 95.

NMS_WIN32_Intel 2.1.9.0

2.1.9.0

PC: Kodiak 1 Adapter hangs during loopback testing in Proset2

Added some more TRACE messages.

Modified CModel::Save() method to delay the m_pDevices->Save() method call until the end.

2.0.24.71m

NMS_WIN32_Intel version 2.0.24.7 with E100M mobile support and NT fix for RAS

On NT4, if registry "DisableNMSCfgFlashAccess" is set and base driver is not loaded, dont access the flash so that modem stays enabled - DCS 12075

2.0.24.34m

On NT4, if registry "DisableNMSCfgFlashAccess" is set and base driver is not loaded, dont access the flash so that modem stays enabled - DCS 12075

2.1.8.0

Added check in the code to not to touch the H/W using the NMSCfg Driver on the PnP OS

2.1.7.0

Soldotna Details button does not display correct information Bus Speed & Width

NMS_WIN64_Intel 2.1.9.0

2.1.9.0

PC: Kodiak 1 Adapter hangs during loopback testing in Proset2

Added some more TRACE messages.

Modified CModel::Save() method to delay the m_pDevices->Save() method call until the end.

2.1.8.0

Wrong comparison of the Controller IDs

Added check in the code to not to touch the H/W using the NMSCfg Driver on the PnP OS, except during the Diagnostic & Flash update.

2.1.7.0

Soldotna Details button does not display correct information Bus Speed & Width

Proset+_Win95_Intel 3.205

3.205

Proset+ does not work in Win95, had to change PROKDD_VERSION from 0x0022 to 0x0023 to match with the version which NMSCfg driver understand, this is needed for PCI scan to work properly. While investigating found out that diagnostics for Windows 95 is not working. Current workaround is remove diagnostics tab from PROSet+ for Win 95

3.204

Added support of regular and mobile lavon adapter.

PROSetII-Intel 5.3.7.0

5.3.7.0

Corrected implementation for handing out string in case for Windows NT 4, during installation for Dayville adapters.

PROSetII-Reg_All 6.13

6.13

Updated GigaNIC info per "Pacific City NoSec 6.1" project v6.1c0478 Net8254i.INF.

Setup_BaseDriver_Install 6.1.6.0

6.1.6.0

Modified SetupBD not having to preinstall the 64 bit INFs to 32 bit machines.

6.1.5.0

Fixed static link problem for Setupapi.dll in Windows NT40

6.1.4.0

Fixed Bug 16238 and 13888

Setup_MI_64 6.1.18.061

6.1.18.061

New Base driver MSM

6.1.17.061

Include PROSetp.reg v6.13. Add prevention of downgrade from newer version to avoid PC6.1 installing over NCS PC6.3.

6.1.16.061

Include PROSetp.reg v6.13. Add prevention of downgrade from newer version to avoid PC6.1 installing over NCS PC6.3.

6.1.15.061

New NMS binaries

6.1.14.061

New Base driver MsM

6.2.5.0

Include PROSet 5.2.38.0

6.1.13.061
Fixes Showstopper 16238

6.1.12.061
Include NMS 2.1.8.0

6.1.11.061
New SNMP MM version (1.13..0.0)

6.1.10.061
Include PROSet 5.3.7.0 and NMS 2.1.7.0.

Setup_PROSet_MSI 6.1.16.061

6.1.16.061
Include NMS 2.1.9.0

6.1.15.061
Include latest wireless components to fix wireless upgrade issue and PROSetp.cpl disable issue on NT4.
Also wireless component reference count is added in this build.

6.2.5.0
Include PROSet 5.3.28.0

6.1.14.061
Include NMS 2.1.8.0

6.1.13.061
Include PROSet 5.3.7.0 and NMS 2.1.7.0.

Setup_PROSet64_MSI 6.1.15.061

6.1.15.061
New NMS binaries

6.2.5.0
Include PROSet 5.2.38.0

6.1.14.061
Include NMS 2.1.8.0

6.1.13.061
Include PROSet 5.3.7.0 and NMS 2.1.7.0.

6.1.12.061a
Include PROSet 5.3.6.0

Tools-Diag1000_EFI_Intel 4.1.8.3

4.1.8.3
Added message "Reading Adapter Configuration..." which displays when the user selects "View Adapter Configuration" option from "Main Menu".
Increased max wait for link status check to 4 seconds because some adapters take a few seconds to establish link after an adapter reset.

4.1.8.2

Fixed the View Adapter Configuration menu to display adapter link status correctly.
Rolled rev to 4.1.8.2.

4.1.8.1

Network test now sends 5000 packets instead of 500. This build is using new CUDL binaries to fix sender/responder bug.

4.0.7.1

DIAG1000 v4.0.7.1

Fix to include copyright string in version and usage statements.

Fixed to display correct description string.

Compiles with NAL 0.57.62.1, CUDL 0.97.5.1, GAL 0.94.0.5.

4.0.7.0

- Rolled rev to 4.0.7.0.

- Added delay loop to link test to wait for link to reestablish before testing for link. This was affecting Soldotna on EFI64.

Tools-IBACfg_All_Intel v1.04

v1.04

Fixed a grammar issue and a destroyed character in the warning screen

Tools-IBAUtl_DOS_Intel v1.12_g1103_e4103

v1.12_g1103_e4103

The tool was mis-reporting the enable/disable of the Flash on Soldotna. By adding a check to validate the flash.

v1.11_g1103_e4103

Fixed an issue where the wrong WOL bit was being set.

v1.10_g1103_e4103

Includes the boot agent that fixes the following:

Fixed showstopper 16468 Soldotna's not booting on 440ZX systems.

The ACPI scanning code was causing system hangs only on the 440ZX chipset. Added code to not try scanning on the 440ZX. All three systems in the defect entry all had the same chipset.

Unattended_Install_All 2.3

2.3

Copying w2kupdat.exe from \windows\update\win2k_xp

2.2

Added legal disclaimer to readme text files.

Unix-UW7DDI8_8254x_Ravenbay_Intel 6.1.10

6.1.10

Now support generic device IDs such as non-supported Cordova-R IDs. Showstopper SCR #16561

Win64_NDIS5_8255x_All 6.1.3a

6.1.3a

Fixed installation issue with Windows 95 and Windows NT. Updated ASF actions.

6.1.3

Special release for PC 6.1 v6.1.3. Fixed installation issue with Windows NT4 and Windows 95.