



Product: SiS USB2 Driver

Date: 11/18/2004

Document Type : Release Note

Driver. No.: 1.05

SiS USB2 Driver [V1.05]

1. The USB2 logo driver v1.05, no USB driver update from USB driver v1.04.
2. The USB2.0 device can now be support by Microsoft inbox driver under Windows XP SP1, Windows XP SP2 and Windows 2000 SP4 systems.

Modification

1. Fix the defect of detecting chipset version that may cause 962/962L/963/963L platforms fail to install the USB2 driver.