



Product: SiS USB Patch

Date: 05/10/2004

Document Type : Release Note

Patch. No.: 0.2

SiS NUSB Patch Purpose

1. While using the SiSUSB2 driver which supports Windows XP and Windows 2000 only, may cause a yellow mark on Universal Serial Bus Controllers of device manager under Windows 98 and Windows ME systems. This patch is made for eliminating this yellow mark.
2. The patch is suitable for SiS964/964L/963/963L/962/962L series chips.

Modification

1. Add SiS965/965L chips support.